

Repair Movies

- mechanical -



Xperia™ Z2 Tablet

SGP511, SGP512, SGP521, SGP541, SGP551, SGP561

CONTENTS

1 Movies 3

1.1 Disassembly 3

1.2 Reassembly 4

2 Revision History 5

To view the embedded repair movies in this document, Acrobat Reader version 8 (or later) and Flash Player version 8 (or later) must be installed on your computer.

For best picture quality, select “Actual size” or “100%” as zoom level in Acrobat Reader. To magnify while keeping an acceptable picture quality, increase the zoom level to 200%.

If the movies appear to be jerky or blurred when viewing on-line, this is probably caused by the connection speed being too slow. In that case, right-click with the mouse on the document name and select Save Target As to download the repair movie document for off-line viewing.

For general information about repair movies, refer to 1220-1333: Generic Repair Manual - mechanical


1 Movies

1.1 Disassembly

SGP511,SGP512,SGP521,SGP541,SGP551,SGP561

The Disassembly is done to the following modules:

- Display Assembly RoW
- Holder LCD Relay BtB
- Relay LCD Flex
- Plate Audio Jack
- Holder Audio Jack
- Cap SP Assembly (Left)
- Audio Jack Flex
- NFC antenna
- Camera 8 MPixel
- Holder Main CAM
- BT + WLAN + GPS Antenna
- Sheet Chat CAM
- Camera 2 MPixel
- Sensor Flex
- Main Antenna
- Holder PBA screw
- Carrier Frame Sub PBA
- Plate USB
- Main PBA
- Magnetic charger flex
- Cushion SPK R
- Cap SP Assembly (Right)
- SP Flex
- Adhesive Battery (a) and Battery (b)
- Key Flex module




1.2 Reassembly

SGP511,SGP512,SGP521,SGP541,SGP551,SGP561

The Re-assembly is done to the following modules:

- Key Flex module
- Adhesive Battery (a) and Battery (b)
- SP Flex
- Cap SP Assembly (Right)
- Cushion SPK R
- Magnetic charger flex
- Main PBA
- Plate USB
- Carrier Frame Sub PBA
- Holder PBA screw
- Main Antenna
- Sensor Flex
- Camera 2 MPixel
- Sheet Chat CAM
- BT + WLAN + GPS Antenna
- Holder Main CAM
- Camera 8 Mpixel
- NFC antenna
- Audio Jack Flex
- Cap SP Assembly (Left)
- Holder Audio Jack
- Plate Audio Jack
- Relay LCD Flex
- Holder Relay LCD BtB
- Display Assembly RoW



2 Revision History

Rev.	Date	Changes / Comments
1	2014-Mars-18	Initial release
2	2014-April-11	Updated with SGP551
3	2014-July-01	Updated with SGP561