

Update CS-Everest for Xperia L1 support

Doc ID	SI13181	Updated:	04/18/2017
Version:	6.0	Categories:	Xperia L1/L1 Dual SIM (G33)
Status:	Published	Available To:	Mechanical
Published date:	04/18/2017	Author:	jpmawa0005

Service Information (Mechanical)

This document is applicable for:

Xperia L1 (G3311, G3312, G3313)

Background:

CS-Everest supports calibration APK installation for Xperia L1 too.

Instructions:

Use CS-Everest whose version is **3 or later**.

1. Access to Repair Information

Access to Repair Information, and find RE4251 : Repair- Mechanical - Tools and Equipment (including Repair Software)

Confirm a version of "CS-Everest:" is **3 or later**.

CS-Everest:	1309-7255 3	2017-04-17
-------------	-------------	------------

2. Download and Execute

Download "Repair_Software_File_CS-Everest_1309-7255_X_1.zip". (X : document version)

Unzip the archive file, and find "ReadMe.txt" written the installation instruction.

This information is provided by:

Customer Services

Sony Mobile Communications

Disclaimer:

Sony Mobile Communications reserves the right to reject claims which are not in accordance to this SI.