

Mastertabelle

Produkt

Datei

Name

BOM-130269-76-000

M65

BOM-130269-76-000

Sparka

Status	Mitteilungs-Nr.	Datum	Name
77		30.09.2005	Pieper
76	32226	30.09.2005	Pieper
75	32223	29.09.2005	Pieper
74	32116	27.09.2005	Pieper

Funkgerät	Swap-Baugruppe	SW LG TG	Standard-I	Kunden-I	SIM-Lock	Level	Tegic	Sprache	Gerätevariante
L36880-Q7150-A10		12 01 00	M65_1_Standard_12_0001.map	M65_2_xx-FFS-LG01_12_0237.map /.xfs		0		M65_1201.xl	M65/BOARD/SWAP
L36880-Q7150-A11		12 01 00	M65_1_Standard_12_0001.map	M65_2_xx-FFS-LG01_12_0237.map /.xfs	L55_Nw-prepared_001.sim	1		M65_1201.xl	M65/BOARD/SWAP/SL1
L36880-Q7150-A20		12 01 00	M6V_1_Standard_12_0001.map	M6V_2_au-VF_12_0237.map /.xfs		0		M6V_1201.xl	M65/VDF/BOARD/SWAP
L36880-Q7150-A26		12 01 00	M65_1_Standard_12_0001.map	M65_2_xx-FFS-LG01_12_0237.map /.xfs	L55_NwSub-prepared_001.sim	16		M65_1201.xl	M65/BOARD/SWAP/SL16
L36880-Q7150-A80		12 08 00	M6C_1_Standard_12_0001.map	M6C_2_xx-FFS-LG08_12_0237.map /.xfs		0		M6C_1208.xl	M65/BOARD/SWAP/LG8
L36880-Q7150-A99		12 01 00	M65_1_Standard_12_0001.map	M65_2_xx-FFS-LG01_12_0237.map /.xfs		0		M65_1201.xl	M65/BOARD/SWAP
L36880-Q7150-C10		12 08 00	M6C_1_Standard_12_0001.map	M6C_2_xx-FFS-LG08_12_0237.map /.xfs		0		M6C_1208.xl	M65/BOARD/SWAP/LG8
L36880-Q7150-R10		12 08 00	M6C_1_Standard_12_0001.map	M6C_2_xx-FFS-LG08_12_0237.map /.xfs		0		M6C_1208.xl	M65/BOARD/SWAP/LG8
S30880-S7150-A100		50 01 00	M65_1_Standard_50_0001.map	M65_2_xx-FFS-LG01_50_0409.map /.xfs		0		M65_5001.xl	M65/CG/INT.
S30880-S7150-A101		25 01 00	M65_1_Standard_25_0001.map	M65_2_de-o2-post_25_0310.map /.xfs		0		M65_2501.xl	M65/CG/O2DE
S30880-S7150-A102		25 01 00	M65_1_Standard_25_0001.map	M65_2_uk-UKStandard_25_0310.map /.xfs		0		M65_2501.xl	M65/CG/GB/RETAIL/0
S30880-S7150-A104		50 01 00	M65_1_Standard_50_0001.map	M65_2_es-Iberia_50_0409.map /.xfs		0		M65_5001.xl	M65/CG/ES/IBERIA R/0
S30880-S7150-A105		50 01 00	M65_1_Standard_50_0001.map	M65_2_it-SMERetail_50_0409.map /.xfs		0		M65_5001.xl	M65/CG/SME/RETAIL/0
S30880-S7150-A106		43 01 00	M65_1_Standard_43_0001.map	M65_2_pt-TMN-i9_43_0363.map /.xfs	L55_TMN_001.sim	1		M65_4301.xl	M65/CG/PT/TMN/1
S30880-S7150-A108		43 01 00	M65_1_Standard_43_0001.map	M65_2_pt-Optimus-Zone_43_0363.map /.xfs	L55_Optimus_001.sim	1		M65_4301.xl	M65/CG/PT/OPTIMUS/1
S30880-S7150-A109		50 01 00	M65_1_Standard_50_0001.map	M65_2_gr-SMERetail_50_0409.map /.xfs		0		M65_5001.xl	M65/CG/GR/RETAIL/0
S30880-S7150-A112		43 01 00	M65_1_Standard_43_0001.map	M65_2_de-BRDHandel_43_0363.map /.xfs		0		M65_4301.xl	M65/CG/DE/RETAIL/0
S30880-S7150-A113		50 01 00	M65_1_Standard_50_0001.map	M65_2_fr-Retail_50_0409.map /.xfs		0		M65_5001.xl	M65/CG/FR/RETAIL/0
S30880-S7150-A114		50 01 00	M65_1_Standard_50_0001.map	M65_2_la-Retail_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		M65_5001.xl	M65/CG/LAM/RETAIL/1
S30880-S7150-A115		50 01 00	M65_1_Standard_50_0001.map	M65_2_xx-FFS-LG01_50_0409.map /.xfs		0		M65_5001.xl	M65/CB/INT.
S30880-S7150-A116		25 01 00	M65_1_Standard_25_0001.map	M65_2_de-o2-post_25_0310.map /.xfs		0		M65_2501.xl	M65/CB/DE/O2/0
S30880-S7150-A117		43 01 00	M65_1_Standard_43_0001.map	M65_2_de-BRDHandel_43_0363.map /.xfs		0		M65_4301.xl	M65/CB/DE/RETAIL/0
S30880-S7150-A118		50 01 00	M65_1_Standard_50_0001.map	M65_2_es-Iberia_50_0409.map /.xfs		0		M65_5001.xl	M65/CB/IBERIA/0
S30880-S7150-A119		50 01 00	M65_1_Standard_50_0001.map	M65_2_br-Retail_50_0409.map /.xfs		0		M65_5001.xl	M65/CG/BR/RETAIL/0
S30880-S7150-A120		41 01 00	M65_1_Standard_41_0001.map	M65_2_ch-Orange_41_0356.map /.xfs		0		M65_4101.xl	M65/CB/CH/ORANGE/0
S30880-S7150-A121		43 01 00	M65_1_Standard_43_0001.map	M65_2_mx-Telcel_43_0363.map /.xfs	L55_Telcel_Mexico_001.sim	1		M65_4301.xl	M65/CG/MX/TELCEL/0
S30880-S7150-A122		16 01 00	M65_1_Standard_16_0001.map	M65_2_cl-TM_16_0410.map /.xfs	L55_TM-Chile_001.sim	3		M65_1601.xl	M65/CG/CL/TM/1
S30880-S7150-A123		50 01 00	M65_1_Standard_50_0001.map	M65_2_it-SMERetail_50_0472.map /.xfs		0		M65_5001.xl	M65/CB/SME/RETAIL/0
S30880-S7150-A125		50 01 00	M65_1_Standard_50_0001.map	M65_2_cl-EPCS_50_0409.map /.xfs	L55_Entel-Chile_002.sim	1		M65_5001.xl	M65/CG/CL/EPCS/1
S30880-S7150-A126		50 01 00	M65_1_Standard_50_0001.map	M65_2_cl-EPCS_50_0409.map /.xfs	L55_Entel-Chile_002.sim	1		M65_5001.xl	M65/CB/CL/EPCS/1
S30880-S7150-A127		16 01 00	M65_1_Standard_16_0001.map	M65_2_cl-TM_16_0410.map /.xfs	L55_TM-Chile_001.sim	3		M65_1601.xl	M65/CB/CL/TM/1
S30880-S7150-A128		43 01 00	M65_1_Standard_43_0001.map	M65_2_fr-Orange_43_0395.map /.xfs	L55_Orange-France_002.sim	1		M65_4301.xl	M65/CB/FR/ORANGE/1
S30880-S7150-A129		50 01 00	M65_1_Standard_50_0001.map	M65_2_tr-Turkey-Retail_50_0409.map /.xfs		0		M65_5001.xl	M65/CB/TR/RETAIL/0
S30880-S7150-A140		50 95 00	M65_1_Standard_50_0001.map	M65_2_co-OLA_50_0473.map /.xfs	L55_OLA_001.sim	1		M65_5095.xl	M65/CG/CO/OLA/1
S30880-S7150-A141		50 01 00	M65_1_Standard_50_0001.map	M65_2_uk-Retail-WorldPhone_50_0489.map /.xfs		0		M65_5001.xl	M65/CG/AFR/WORLD PH/0
S30880-S7150-A150		25 01 00	M65_1_Standard_25_0001.map	M65_2_de-o2-post_25_0310.map /.xfs		0		M65_2501.xl	M65/CG/DE/O2-BIKE/0
S30880-S7150-A151		50 01 00	M65_1_Standard_50_0001.map	M65_2_br-Oi_50_0409.map /.xfs	L55_Oi_Telemar_001.sim	1		M65_5001.xl	M65/CG/BR/OI/1BIKE-O-METER
S30880-S7150-A152		50 01 00	M65_1_Standard_50_0001.map	M65_2_br-Retail_50_0409.map /.xfs		0		M65_5001.xl	M65/CG/BR/RETAIL/0BIKE-O-METER
S30880-S7150-A201		50 02 00	M65_1_Standard_50_0001.map	M65_2_nc-Retail-NORDAN_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		M65_5002.xl	M65/CG/NODK/RETAIL/1
S30880-S7150-A202		50 02 00	M65_1_Standard_50_0001.map	M65_2_sw-dk-ComviqGolive_50_0472.map /.xfs	L55_Comviq-Sweden_001.sim	1		M65_5002.xl	M65/CG/SE/COMVIQ/1
S30880-S7150-A203		50 02 00	M65_1_Standard_50_0001.map	M65_2_dk-SWEFIN-Retail_50_0409.map /.xfs		0		M65_5002.xl	M65/CG/FI-SE/RETAIL/0
S30880-S7150-A204		50 02 00	M65_1_Standard_50_0001.map	M65_2_sw-Telia-PostGo_50_0472.map /.xfs	L55_TeliaSweden_001.sim	1		M65_5002.xl	M65/CG/SE/TELIA/1
S30880-S7150-A205		50 02 00	M65_1_Standard_50_0001.map	M65_2_nl-Retail_50_0409.map /.xfs		0		M65_5002.xl	M65/CG/NL/RETAIL/0
S30880-S7150-A206		50 02 00	M65_1_Standard_50_0001.map	M65_2_no-Telenor_50_0409.map /.xfs	L55_Telenor-Norway_001.sim	16		M65_5002.xl	M65/CG/NO/TELENOR/1
S30880-S7150-A207		50 02 00	M65_1_Standard_50_0001.map	M65_2_nc-Retail-NORDAN_50_0409.map /.xfs		0		M65_5002.xl	M65/CG/NODK/RETAIL/0
S30880-S7150-A208		25 02 00	M65_1_Standard_25_0001.map	M65_2_uk-O2-Contract_25_0310.map /.xfs		0		M65_2502.xl	M65/CG/UK/O2 UK/0
S30880-S7150-A210		50 02 00	M65_1_Standard_50_0001.map	M65_2_be-BERetail_50_0409.map /.xfs		0		M65_5002.xl	M65/CG/BE/RETAIL/0
S30880-S7150-A212		25 02 00	M65_1_Standard_25_0001.map	M65_2_uk-UKStandard_25_0310.map /.xfs		0		M65_2502.xl	M65/CG/UK/RETAIL/0
S30880-S7150-A213		12 02 00	M65_1_Standard_12_0001.map	M65_2_uk-Vodafone-Corporate_12_0237.map /.xfs	L55_Vodafone-UK_001.sim	1		M65_1202.xl	M65/CG/UK/VDF/1

Mastertabelle

Produkt

Datei

Name

BOM-130269-76-000

M65

BOM-130269-76-000

Sparka

Funkgerät	Swap-Baugruppe	SW LG TG	Standard-I	Kunden-I	SIM-Lock	Level	Tegic	Sprache	Gerätevariante
S30880-S7150-A214		50 02 00	M65_1_Standard_50_0001.map	M65_2_nc-Retail-NORDAN_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		M65_5002.xl	M65/GS/NODK/RETAIL/1
S30880-S7150-A215		43 02 00	M65_1_Standard_43_0001.map	M65_2_uk-Orange-OBS_43_0394.map /.xfs	L55_OrangeUK_001.sim	1		M65_4302.xl	M65/CB/UK/ORANGE/1/OBS
S30880-S7150-A217		50 02 00	M65_1_Standard_50_0001.map	M65_2_be-BERetail_50_0409.map /.xfs		0		M65_5002.xl	M65/CB/BE/RETAIL/0
S30880-S7150-A218		50 02 00	M65_1_Standard_50_0001.map	M65_2_dk-SWEFIN-Retail_50_0409.map /.xfs		0		M65_5002.xl	M65/CB/FI-SE/RETAIL/0
S30880-S7150-A219		50 02 00	M65_1_Standard_50_0001.map	M65_2_nc-Retail-NORDAN_50_0409.map /.xfs		0		M65_5002.xl	M65/CB/NODK/RETAIL/0
S30880-S7150-A220		25 02 00	M65_1_Standard_25_0001.map	M65_2_uk-UKStandard_25_0310.map /.xfs		0		M65_2502.xl	M65/CB/GB/RETAIL/0
S30880-S7150-A221		25 02 00	M65_1_Standard_25_0001.map	M65_2_uk-O2-Contract_25_0310.map /.xfs		0		M65_2502.xl	M65/CB/GB/O2 UK/0
S30880-S7150-A222		12 02 00	M65_1_Standard_12_0001.map	M65_2_uk-Vodafone-Corporate_12_0237.map /.xfs	L55_Vodafone-UK_001.sim	1		M65_1202.xl	M65/CB/GB/VF/1
S30880-S7150-A223		12 02 00	M65_1_Standard_12_0001.map	M65_2_uk-Vodafone-Corporate_12_0237.map /.xfs		0		M65_1202.xl	M65/CG/GB/VF/0
S30880-S7150-A224		12 02 00	M65_1_Standard_12_0001.map	M65_2_uk-Vodafone-Corporate_12_0237.map /.xfs		0		M65_1202.xl	M65/CB/GB/VF/0
S30880-S7150-A225		50 02 00	M65_1_Standard_50_0001.map	M65_2_nl-Retail_50_0409.map /.xfs		0		M65_5002.xl	M65/CB/NL/RETAIL/0
S30880-S7150-A226		50 02 00	M65_1_Standard_50_0001.map	M65_2_no-Telenor_50_0409.map /.xfs	L55_Telenor-Norway_001.sim	16		M65_5002.xl	M65/CB/NO/TELENO/1
S30880-S7150-A227		50 02 00	M65_1_Standard_50_0001.map	M65_2_dk-Sonofon-graysilver_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		M65_5002.xl	M65/GS/DK/SONOFON/1
S30880-S7150-A228		50 02 00	M65_1_Standard_50_0001.map	M65_2_sw-dk-ComviqGolive_50_0472.map /.xfs	L55_Comviq-Sweden_001.sim	1		M65_5002.xl	M65/CB/SE/COMVIQ/1
S30880-S7150-A229		50 02 00	M65_1_Standard_50_0001.map	M65_2_sw-Telia-PostGo_50_0472.map /.xfs	L55_TeliaSweden_001.sim	1		M65_5002.xl	M65/CB/SE/TELIA/1
S30880-S7150-A230		41 02 00	M65_1_Standard_41_0001.map	M65_2_no-NetCom_41_0362.map /.xfs	L55_NetCom_003.sim	16		M65_4102.xl	M65/CB/NO/NETCOM/1
S30880-S7150-A300		50 03 00	M65_1_Standard_50_0001.map	M65_2_ua-retail_50_0409.map /.xfs		0		M65_5003.xl	M65/CG/UA/RETAIL/0
S30880-S7150-A301		50 03 00	M65_1_Standard_50_0001.map	M65_2_lt-Baltics_50_0409.map /.xfs		0		M65_5003.xl	M65/CG/LT/LV/RETAIL/0
S30880-S7150-A302		50 03 00	M65_1_Standard_50_0001.map	M65_2_ee-emtriletele2_50_0409.map /.xfs		0		M65_5003.xl	M65/CG/EE/RETAIL/0
S30880-S7150-A303		50 03 00	M65_1_Standard_50_0001.map	M65_2_ua-retail_50_0409.map /.xfs		0		M65_5003.xl	M65/CB/UA/RETAIL/0
S30880-S7150-A304		50 03 00	M65_1_Standard_50_0001.map	M65_2_lt-Baltics_50_0409.map /.xfs	A52_Baltics_001.sim	1		M65_5003.xl	M65/CB/LTLV/RETAIL/1
S30880-S7150-A390		50 03 00	M65_1_Standard_50_0001.map	M65_2_ru-RussianRollingStone_50_0444.map /.xfs		0		M65_5003.xl	M65/CG/RU/RETAIL/0
S30880-S7150-A391		58 03 00	M65_1_Standard_58_0001.map	M65_2_ru-RussianRollingStone_58_0486.map /.xfs		0		M65_5803.xl	M65/CB/RU/ULTRASTA/0
S30880-S7150-A392		50 03 00	M65_1_Standard_50_0001.map	M65_2_ru-RussianRetail_50_0409.map /.xfs		0		M65_5003.xl	M65/CG/RU/RETAIL/0BIKE-O-METER
S30880-S7150-A393		50 03 00	M65_1_Standard_50_0001.map	M65_2_ru-RussianRetail_50_0409.map /.xfs		0		M65_5003.xl	M65/CB/RU/RETAIL/0BIKE-O-METER
S30880-S7150-A400		50 04 00	M65_1_Standard_50_0001.map	M65_2_pl-Polkomtel_50_0409.map /.xfs	L55_POLKOMTEL_001.sim	1		M65_5004.xl	M65/CG/PL/POLKOMTE/1
S30880-S7150-A401		50 04 00	M65_1_Standard_50_0001.map	M65_2_pl-Centertel_50_0409.map /.xfs	L55_Centertel-POL_001.sim	1		M65_5004.xl	M65/CG/PL/CENTERTE/1
S30880-S7150-A402		50 04 00	M65_1_Standard_50_0001.map	M65_2_pl-PTC_50_0409.map /.xfs	L55_PTC-POL_001.sim	1		M65_5004.xl	M65/CG/PL/ERA/1
S30880-S7150-A403		50 04 00	M65_1_Standard_50_0001.map	M65_2_cz-CeskyMobil_50_0409.map /.xfs		0		M65_5004.xl	M65/CG/CZ/CESKYMOB/0
S30880-S7150-A404		50 04 00	M65_1_Standard_50_0001.map	M65_2_xx-FFS-LG04_50_0409.map /.xfs		0		M65_5004.xl	M65/CG/CZ-S/RETAIL/0
S30880-S7150-A406		50 04 00	M65_1_Standard_50_0001.map	M65_2_at-OneConnect_50_0472.map /.xfs	L55_one connect_001.sim	1		M65_5004.xl	M65/CG/AT/ONE/1
S30880-S7150-A407		50 04 00	M65_1_Standard_50_0001.map	M65_2_at-Telering_50_0472.map /.xfs	L55_Telering_001.sim	1		M65_5004.xl	M65/CG/AT/TELERING/1
S30880-S7150-A408		50 04 00	M65_1_Standard_50_0001.map	M65_2_pl-PTC_50_0409.map /.xfs	L55_PTC-POL_001.sim	1		M65_5004.xl	M65/GS/PL/ERA/1
S30880-S7150-A409		43 04 00	M65_1_Standard_43_0001.map	M65_2_hr-HTmobile_43_0363.map /.xfs	L55_Cronet_001.sim	1		M65_4304.xl	M65/GS/HR/HTMOBILE/1
S30880-S7150-A410		50 04 00	M65_1_Standard_50_0001.map	M65_2_si-Slovenia-mobitel_50_0472.map /.xfs	L55_Mobitel_001.sim	1		M65_5004.xl	M65/CG/SI/MOBITEL/1
S30880-S7150-A411		50 04 00	M65_1_Standard_50_0001.map	M65_2_sk-EuroTel_50_0409.map /.xfs		0		M65_5004.xl	M65/CG/SK/TMO/0
S30880-S7150-A412		50 04 00	M65_1_Standard_50_0001.map	M65_2_si-Slovenia-simobil_50_0472.map /.xfs	L55_SIMOBIL_002.sim	1		M65_5004.xl	M65/CG/SI/SIMOBILE/1
S30880-S7150-A414		50 04 00	M65_1_Standard_50_0001.map	M65_2_hr-RetailVariant_50_0409.map /.xfs		0		M65_5004.xl	M65/CG/HR/RETAIL/0
S30880-S7150-A415		50 04 00	M65_1_Standard_50_0001.map	M65_2_hu-PannonDjuice_50_0472.map /.xfs	L55_Pannon-Hungary_001.sim	1		M65_5004.xl	M65/CG/HU/PANNONDJ/1
S30880-S7150-A417		50 04 00	M65_1_Standard_50_0001.map	M65_2_si-Slovenia-mobitel_50_0472.map /.xfs	L55_Mobitel_001.sim	1		M65_5004.xl	M65/CB/SI/MOBITEL/1
S30880-S7150-A418		50 04 00	M65_1_Standard_50_0001.map	M65_2_pl-PTC_50_0409.map /.xfs	L55_PTC-POL_001.sim	1		M65_5004.xl	M65/CG/PL/ERA/1
S30880-S7150-A419		50 04 00	M65_1_Standard_50_0001.map	M65_2_at-Telering_50_0472.map /.xfs	L55_Telering_001.sim	1		M65_5004.xl	M65/CB/AT/TELERING/1
S30880-S7150-A420		50 04 00	M65_1_Standard_50_0001.map	M65_2_at-OneConnect_50_0472.map /.xfs	L55_one connect_001.sim	1		M65_5004.xl	M65/CB/AT/ONE/1
S30880-S7150-A421		50 04 00	M65_1_Standard_50_0001.map	M65_2_si-Slovenia-simobil_50_0472.map /.xfs	L55_SIMOBIL_002.sim	1		M65_5004.xl	M65/CG/HU/SIMO-BIKE/1
S30880-S7150-A422		50 04 00	M65_1_Standard_50_0001.map	M65_2_xx-FFS-LG04_50_0409.map /.xfs		0		M65_5004.xl	M65/CB/CZ/RETAIL/0
S30880-S7150-A500		50 05 00	M65_1_Standard_50_0001.map	M65_2_xx-FFS-LG05_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		M65_5005.xl	M65/CG/RO/BG-RETAI/1
S30880-S7150-A501		50 05 00	M65_1_Standard_50_0001.map	M65_2_xx-FFS-LG05_50_0409.map /.xfs		0		M65_5005.xl	M65/CB/BG-RO/RETAIL/0
S30880-S7150-A600		50 06 00	M65_1_Standard_50_0001.map	M65_2_ae-MiddleEast-Retail_50_0409.map /.xfs		0		M65_5006.xl	M65/CG/MID/RETAIL/0/MIDDLE EAST
S30880-S7150-A601		50 06 00	M65_1_Standard_50_0001.map	M65_2_za-Africa-Retail_50_0409.map /.xfs		0		M65_5006.xl	M65/CG/AFR/RETAIL/0
S30880-S7150-A602		50 06 00	M65_1_Standard_50_0001.map	M65_2_ae-MiddleEast-Retail_50_0409.map /.xfs		0		M65_5006.xl	M65/CB/ME/RETAIL/0
S30880-S7150-A700		50 07 00	M65_1_Standard_50_0001.map	M65_2_ap-APACINT_50_0424.map /.xfs		0		M65_5007.xl	M65/CG/APAC
S30880-S7150-A701		50 07 00	M65_1_Standard_50_0001.map	M65_2_au-AustraliaNZ-RETAIL_50_0409.map /.xfs		0		M65_5007.xl	M65/CG/AU
S30880-S7150-A702		50 07 00	M65_1_Standard_50_0001.map	M65_2_th-Thai-S_50_0409.map /.xfs		0		M65_5007.xl	M65/CG/TH

Mastertabelle

Produkt

Datei

Name

BOM-130269-76-000

M65

BOM-130269-76-000

Sparka

Funkgerät	Swap-Baugruppe	SW LG TG	Standard-I	Kunden-I	SIM-Lock	Level	Tegic	Sprache	Gerätevariante
S30880-S7150-A703		50 07 00	M65_1_Standard_50_0001.map	M65_2_au-AustraliaNZ-RETAIL_50_0409.map /.xfs		0		M65_5007.xl	M65/CG/AU/RETAIL/0
S30880-S7150-A704		50 07 00	M65_1_Standard_50_0001.map	M65_2_ap-APACINT_50_0424.map /xfs		0		M65_5007.xl	M65/CB/APAC/RETAIL/0
S30880-S7150-A705		50 07 00	M65_1_Standard_50_0001.map	M65_2_au-AustraliaNZ-RETAIL_50_0409.map /.xfs		0		M65_5007.xl	M65/CB/AU/RETAIL/0
S30880-S7150-A801		50 08 00	M6C_1_Standard_50_0001.map	M6C_2_hm-HSM_50_0409.map /xfs		0		M6C_5008.xl	M65/CG/HSM
S30880-S7150-A802		50 08 00	M6C_1_Standard_50_0001.map	M6C_2_tw-Taiwan_50_0409.map /xfs		0		M6C_5008.xl	M65/CG/TW
S30880-S7150-A803		50 08 00	M6C_1_Standard_50_0001.map	M6C_2_sg-Singapore-RM_50_0409.map /xfs		0		M6C_5008.xl	M65/CB/SG/RETAIL/0
S30880-S7150-A804		50 08 00	M6C_1_Standard_50_0001.map	M6C_2_hm-HSM_50_0409.map /xfs		0		M6C_5008.xl	M65/CB/HK/RETAIL/0
S30880-S7150-A850		50 08 00	M6C_1_Standard_50_0001.map	M6C_2_tw-Taiwan_50_0409.map /xfs		0		M6C_5008.xl	M65/CG/TW/DISTRIBU/0
S30880-S7150-B100		50 01 00	M6V_1_Standard_50_0001.map	M6V_2_de-VF-D2_50_0409.map /xfs		0		M6V_5001.xl	M65/CG/DE/VDF/0
S30880-S7150-B101		50 01 00	M6V_1_Standard_50_0001.map	M6V_2_ch-Swisscom_50_0409.map /xfs		0		M6V_5001.xl	M65/CG/CH/SWISSCOM/0
S30880-S7150-B102		50 01 00	M6V_1_Standard_50_0001.map	M6V_2_pt-VF_50_0409.map /xfs	L55_Telecel_001.sim	1		M6V_5001.xl	M65/CG/PT/VDF/1
S30880-S7150-B105		50 01 00	M6V_1_Standard_50_0001.map	M6V_2_es-VF_50_0409.map /xfs	L55_Vodafone-Spain_001.sim	1		M6V_5001.xl	M65/CG/ES/VDF/1
S30880-S7150-B106		50 01 00	M6V_1_Standard_50_0001.map	M6V_2_gr-VF_50_0409.map /xfs		0		M6V_5001.xl	M65/CG/GR/VDF/0
S30880-S7150-B107		50 01 00	M6V_1_Standard_50_0001.map	M6V_2_au-VF_50_0409.map /xfs		0		M6V_5001.xl	M65/CG/AUNZ/VDF/0
S30880-S7150-B108		50 01 00	M6V_1_Standard_50_0001.map	M6V_2_es-VF_50_0409.map /xfs	L55_Vodafone-Spain_001.sim	1		M6V_5001.xl	M65/CB/ES/VDF/1
S30880-S7150-B109		50 01 00	M6V_1_Standard_50_0001.map	M6V_2_de-VF-D2_50_0409.map /xfs		0		M6V_5001.xl	M65/CB/DE/VDF/0
S30880-S7150-B201		50 02 00	M6V_1_Standard_50_0001.map	M6V_2_nl-VF_50_0409.map /xfs	L55_Vodafone-NL_001.sim	1		M6V_5002.xl	M65/CG/NL/VDF/1
S30880-S7150-B400		50 04 00	M65_1_Standard_50_0001.map	M65_2_de-T-Mobile_50_0472.map /xfs		0		M65_5004.xl	M65/GS/DE/TMO/0
S30880-S7150-B401		50 04 00	M65_1_Standard_50_0001.map	M65_2_uk-T-Mobile_50_0472.map /xfs	L55_T-Mobile-UK_002.sim	1		M65_5004.xl	M65/GS/GB/TMO/1
S30880-S7150-B402		50 04 00	M65_1_Standard_50_0001.map	M65_2_at-T-Mobile_50_0472.map /xfs	L55_Maxmobil_002.sim	1		M65_5004.xl	M65/GS/AT/TMO/1
S30880-S7150-B403		25 04 00	M65_1_Standard_25_0001.map	M65_2_hu-T-Mobile_25_0300.map /xfs	L55_Westel-Hungary_001.sim	1		M65_5004.xl	M65/GS/HU/TMO/1
S30880-S7150-B404		50 04 00	M6V_1_Standard_50_0001.map	M6V_2_at-VF-Mobilcom_50_0409.map /xfs	L55_Mobilkom_001.sim	1		M6V_5004.xl	M65/CG/AT/MOBILK/1
S30880-S7150-B405		50 04 00	M6V_1_Standard_50_0001.map	M6V_2_hu-VF_50_0409.map /xfs	L55_Vodafone-Hungary_001.sim	1		M6V_5004.xl	M65/CG/HU/VDF/1
S30880-S7150-B406		50 04 00	M65_1_Standard_50_0001.map	M65_2_cz-T-Mobile_50_0472.map /xfs		0		M65_5004.xl	M65/GS/CZ/TMO/0
S30880-S7150-B407		25 04 00	M65_1_Standard_25_0001.map	M65_2_hr-T-Mobile_25_0310.map /xfs	L55_Cronet_001.sim	1		M65_2504.xl	M65/GS/HR/TMO HR/1
S30880-S7150-B408		50 04 00	M65_1_Standard_50_0001.map	M65_2_de-T-Mobile_50_0447.map /xfs		0		M65_5004.xl	M65/CB/DE/TMO/0
S30880-S7150-B409		50 04 00	M65_1_Standard_50_0001.map	M65_2_at-T-Mobile_50_0472.map /xfs	L55_Maxmobil_002.sim	1		M65_5004.xl	M65/CB/AT/TMO/1
S30880-S7150-B410		50 04 00	M6V_1_Standard_50_0001.map	M6V_2_at-VF-Mobilcom_50_0409.map /xfs	L55_Mobilkom_001.sim	1		M6V_5004.xl	M65/CB/AT/MOBILKOM/VF/1
S30880-S7150-B412		25 04 00	M6V_1_Standard_25_0001.map	M6V_2_hu-VF_25_0300.map /xfs	L55_Vodafone-Hungary_001.sim	1		M6V_2504.xl	M65/SR/HU/VF/1
S30880-S7150-D100		43 01 00	M65_1_Standard_43_0001.map	M65_2_de-LE-RBINT_43_0363.map /xfs		0		M65_4301.xl	M65/RB/INT/SIEM/0
S30880-S7150-D101		16 01 00	M65_1_Standard_16_0001.map	M65_2_ch-Swisscom-NeutralWEF_16_0305.map /.xfs		0		M65_1601.xl	M65/RB/CH/SIEM/0
S30880-S7150-D102		43 01 00	M65_1_Standard_43_0001.map	M65_2_de-LE-RBINT_43_0363.map /xfs		0		M65_4301.xl	M65/BB/DE/RETAIL/0/LE
S30880-S7150-D103		43 01 00	M65_1_Standard_43_0001.map	M65_2_de-LE-RBINT_43_0363.map /xfs		0		M65_4301.xl	M65/BR/DE/RETAIL/0/LE
S30880-S7150-M119		58 01 00	M65_1_Standard_58_0001.map	M65_2_br-Retail_58_0486.map /xfs		0		M65_5801.xl	M65/CG/BR/RETAIL/0
S30880-S7150-M122		16 01 00	M65_1_Standard_16_0001.map	M65_2_cl-TM_16_0410.map /xfs	L55_TM-Chile_001.sim	3		M65_1601.xl	M65/CG/CL/TM/1
S30880-S7150-M125		50 01 00	M65_1_Standard_50_0001.map	M65_2_cl-EPCS_50_0409.map /xfs	L55_Entel-Chile_002.sim	1		M65_5001.xl	M65/CG/CL/EPCS/1
S30880-S7150-M126		50 01 00	M65_1_Standard_50_0001.map	M65_2_cl-EPCS_50_0409.map /xfs	L55_Entel-Chile_002.sim	1		M65_5001.xl	M65/CB/CL/EPCS/1
S30880-S7150-M127		16 01 00	M65_1_Standard_16_0001.map	M65_2_cl-TM_16_0410.map /xfs	L55_TM-Chile_001.sim	3		M65_1601.xl	M65/CB/CL/TM/1
S30880-S7150-M130		50 01 00	M65_1_Standard_50_0001.map	M65_2_br-Oi_50_0409.map /xfs	L55_Oi Telemar_001.sim	1		M65_5001.xl	M65/CB/BR/OI/1
S30880-S7150-M131		50 01 00	M65_1_Standard_50_0001.map	M65_2_br-Oi_50_0409.map /xfs	L55_Oi Telemar_001.sim	1		M65_5001.xl	M65/CG/BR/OI/1
S30880-S7150-M132		58 01 00	M65_1_Standard_58_0001.map	M65_2_br-Retail_58_0486.map /xfs		0		M65_5801.xl	M65/CB/BR/RETAIL/0
S30880-S7150-M133		50 01 00	M65_1_Standard_50_0001.map	M65_2_br-BrTRallyDosSertoos_50_0433.map /.xfs	L55_Brasil-Telecom_001.sim	1		M65_5001.xl	M65/CG/BR/TEL/RA/1
S30880-S7150-M134		50 01 00	M65_1_Standard_50_0001.map	M65_2_br-TIM_50_0451.map /xfs	L55_TIM-Brazil_001.sim	1		M65_5001.xl	M65/CG/BR/TIM/1
S30880-S7150-M135		50 01 00	M65_1_Standard_50_0001.map	M65_2_br-TIM_50_0451.map /xfs	L55_TIM-Brazil_001.sim	1		M65_5001.xl	M65/CB/BR/TIM/1
S30880-S7150-M138		50 01 00	M65_1_Standard_50_0001.map	M65_2_br-RetailRallyDosSertoos_50_0451.map /.xfs		0		M65_5001.xl	M65/CG/BR/RET/RA/0
S30880-S7150-M139		50 01 00	M65_1_Standard_50_0001.map	M65_2_br-Oi-Kitesurf_50_0498.map /xfs	L55_Oi Telemar_001.sim	1		M65_5001.xl	M65/CG/BR/OI KITE/1
S30880-S7150-M140		50 95 00	M65_1_Standard_50_0001.map	M65_2_co-OLA_50_0473.map /xfs	L55_OLA_001.sim	1		M65_5095.xl	M65/CG/CO/OLA/1
S30880-S7150-M142		50 01 00	M65_1_Standard_50_0001.map	M65_2_br-TelemigCelular_50_0493.map /xfs		0		M65_5001.xl	M65/CB/BR/TELEMIG/0
S30880-S7150-M143		50 01 00	M65_1_Standard_50_0001.map	M65_2_br-BrasilTelecom_50_0494.map /xfs	L55_Brasil-Telecom_001.sim	1		M65_5001.xl	M65/CB/BR/TELECOM/1
S30880-S7150-S100		50 01 00	M65_1_Standard_50_0001.map	M65_2_xx-FFS-LG01_50_0409.map /xfs		0		M65_5001.xl	M65/CG/INT.
S30880-S7150-S115		50 01 00	M65_1_Standard_50_0001.map	M65_2_xx-FFS-LG01_50_0409.map /xfs		0		M65_5001.xl	M65/CB/INT.
S30880-S7150-S700		50 07 00	M65_1_Standard_50_0001.map	M65_2_ap-APACINT_50_0424.map /xfs		0		M65_5007.xl	M65/CG/APAC
S30880-S7150-S701		50 07 00	M65_1_Standard_50_0001.map	M65_2_au-AustraliaNZ-RETAIL_50_0409.map /.xfs		0		M65_5007.xl	M65/CG/AU
S30880-S7150-S702		50 07 00	M65_1_Standard_50_0001.map	M65_2_th-Thai-S_50_0409.map /xfs		0		M65_5007.xl	M65/CG/TH

Mastertabelle

Produkt

Datei

Name

BOM-130269-76-000

M65

BOM-130269-76-000

Sparka

Funkgerät	Swap-Baugruppe	SW LG TG	Standard-I	Kunden-I	SIM-Lock	Level	Tegic	Sprache	Gerätevariante
S30880-S7150-S704		50 07 00	M65_1_Standard_50_0001.map	M65_2_ap-APACINT_50_0424.map /.xfs		0		M65_5007.xl	M65/CB/APAC/RETAIL/0
S30880-S7150-S705		50 07 00	M65_1_Standard_50_0001.map	M65_2_au-AustraliaNZ-RETAIL_50_0409.map /.xfs		0		M65_5007.xl	M65/CB/AU/RETAIL/0
S30880-S7150-S800		25 08 00	M6C_1_Standard_25_0001.map	M6C_2_cn-ChinaRetail_25_0310.map /.xfs		0		M6C_2508.xl	M65/CG/CN
S30880-S7150-S801		50 08 00	M6C_1_Standard_50_0001.map	M6C_2_hm-HSM_50_0409.map /.xfs		0		M6C_5008.xl	M65/CG/HSM
S30880-S7150-S803		50 08 00	M6C_1_Standard_50_0001.map	M6C_2_sg-Singapore-RM_50_0409.map /.xfs		0		M6C_5008.xl	M65/CB/SG/RETAIL/0
S30880-S7150-S804		50 08 00	M6C_1_Standard_50_0001.map	M6C_2_hm-HSM_50_0409.map /.xfs		0		M6C_5008.xl	M65/CB/HK/RETAIL/0
S30880-S7170-A100		44 01 00	M65_1_Standard_44_0001.map	M65_2_de-RescuePhone_44_0364.map /.xfs		0		M65_4401.xl	M65/RP/INT/0
S30880-S7170-A101		44 01 00	M65_1_Standard_44_0001.map	M65_2_de-RescuePhone-BRDHandel_44_0401.m ap /.xfs		0		M65_4401.xl	M65/RP/DE/RETAIL/0
S30880-S7170-A400		44 04 00	M65_1_Standard_44_0001.map	M65_2_si-RescuePhone-mobitel_44_0374.map /.xfs		0		M65_4404.xl	M65/RP/SI/MOBITEL/0
S30880-S7170-A401		44 04 00	M65_1_Standard_44_0001.map	M65_2_cz-RescuePhone-retail_44_0459.map /.xfs		0		M65_4404.xl	M65/RP/CZ/RETAIL/0
S30880-X7150-A100		25 01 00	M65_1_Standard_25_0001.map	M65_2_xx-FFS-LG01_25_0310.map /.xfs	L55_no-id-phone_001.sim	1		M65_2501.xl	M65/CG/NO_ID/A100
S30880-X7150-A101		25 01 00	M65_1_Standard_25_0001.map	M65_2_xx-FFS-LG01_25_0310.map /.xfs	L55_no-id-phone_001.sim	1		M65_2501.xl	M65/GS/NO_ID/A101
S30880-X7150-A102		25 01 00	M65_1_Standard_25_0001.map	M65_2_xx-FFS-LG01_25_0310.map /.xfs	L55_no-id-phone_001.sim	1		M65_2501.xl	M65/CB/NO_ID/A102
S30880-S7150-A103		12 01 00	M65_1_Standard_12_0001.map		%	0		M65_1201.xl	M65/CG/ES/AMENA/1
S30880-S7150-A107		12 01 00	M65_1_Standard_12_0001.map		%	0		M65_1201.xl	M65/CG/PT/VDF/1
S30880-S7150-A110		12 01 00	M65_1_Standard_12_0001.map		%	0		M65_1201.xl	M65/CG/ES/TELEFONI/1
S30880-S7150-A111		12 01 00	M65_1_Standard_12_0001.map		%	0		M65_1201.xl	M65/CG/ES/EUSKALTE/1
S30880-S7150-A124		25 01 00	M65_1_Standard_25_0001.map		L55_Brasil-Telecom_001.sim	1		M65_2501.xl	M65/CG/BR/TELECOM/1
S30880-S7150-A200		12 02 00	M65_1_Standard_12_0001.map		%	0		M65_1202.xl	M65/CG/IE/METEOR I/1
S30880-S7150-A209		12 02 00	M65_1_Standard_12_0001.map			0		M65_1202.xl	M65/CG/IE/IRELAND/0
S30880-S7150-A211		12 02 00	M65_1_Standard_12_0001.map		%	0		M65_1202.xl	M65/CG/IE/O2 IRELA/1
S30880-S7150-A216		12 02 00	M65_1_Standard_12_0001.map			0		M65_1202.xl	M65/CG/UK/BT/0
S30880-S7150-A231		25 02 00	M65_1_Standard_25_0001.map		L55_Virgin Mobile_001.sim	3		M65_2502.xl	M65/CB/GB/VIRGIN/1
S30880-S7150-A250		12 02 00	M65_1_Standard_12_0001.map			0		M65_1202.xl	M65/CG/SE/RETAIL/OBIKE-O-METER
S30880-S7150-A413		12 04 00	M65_1_Standard_12_0001.map		%	0		M65_1204.xl	M65/CG/HR/VIPNET/1
S30880-S7150-A416		25 04 00	M65_1_Standard_25_0001.map			0		M65_2504.xl	M65/CG/CZ/EUROTOL/0
S30880-S7150-A603		50 06 00	M65_1_Standard_50_0001.map			0		M65_5006.xl	M65/CG/AFR/WORLD PH/0
S30880-S7150-B103		12 01 00	M6V_1_Standard_12_0001.map			0		M6V_1201.xl	M65/CG/IT/VDF/0
S30880-S7150-B104		25 01 00	M6V_1_Standard_25_0001.map		%	0		M6V_2501.xl	M65/CG/IE/VDF/1
S30880-S7150-B200		12 02 00	M6V_1_Standard_12_0001.map		%	0		M6V_1202.xl	M65/CG/SE/VDF/1
S30880-S7150-B202		25 02 00	M65_1_Standard_25_0001.map		%	0		M65_2502.xl	M65/CG/UK/VDF/1/CONTRACT
S30880-S7150-M136		50 01 00	M65_1_Standard_50_0001.map		L55_TelecomAmericas_001.sim	1		M65_5001.xl	M65/CG/BR/CLARO/1
S30880-S7150-M137		50 01 00	M65_1_Standard_50_0001.map		L55_TelecomAmericas_001.sim	1		M65_5001.xl	M65/CB/BR/CLARO/1
S30880-S7150-R800		12 08 00	M6C_1_Standard_12_0001.map			0		M6C_1208.xl	M65/CG/CN/RETAIL/0
S30880-S7150-S109		12 01 00	M65_1_Standard_12_0001.map			0		M65_1201.xl	M65/CG/GR/RETAIL/0
S30880-S7150-U200		12 02 00	M65_1_Standard_12_0001.map		%	0		M65_1202.xl	M65/CG/IE/METEOR I/1
S30880-S7170-A102		44 01 00	M65_1_Standard_44_0001.map			0		M65_4401.xl	M65/RP/DE/VF/0
S30880-S7170-A103		44 01 00	M65_1_Standard_44_0001.map		L55_Entel-Chile_002.sim	1		M65_4401.xl	M65/RP/CL/EPCS/1
S30880-S7170-M103		44 01 00	M65_1_Standard_44_0001.map		L55_Entel-Chile_002.sim	1		M65_4401.xl	M65/RP/CL/EPCS/1