

Status	Mitteilungs-Nr.	Datum	Name
81		08.09.2005	Schwenk
80	31484	08.09.2005	Schwenk
79	31196	01.09.2005	Schwenk
78	31032	29.08.2005	Schwenk

Funkgerät	Swap-Baugruppe	SW LG TG	Standard-I	Kunden-I	SIM-Lock	Level	Tegic	Sprache	Gerätevariante
L36880-Q7100-A10	L36880-Q7100-A10	12 01 00	CX65_1_Standard_12_0001.map	CX65_2_xx-FFS-LG01_12_0240.map /.xfs		0		CX651201.xl	CX65/BOARD/SWAP
L36880-Q7100-A11	L36880-Q7100-A11	12 01 00	CX65_1_Standard_12_0001.map	CX65_2_xx-FFS-LG01_12_0240.map /.xfs	L55_Nw-prepared_001.sim	1		CX651201.xl	CX65/BOARD/SWAP/SL1
L36880-Q7100-A20	L36880-Q7100-A20	12 01 00	CX6V_1_Standard_12_0001.map	CX6V_2_de-VF-CX65V_12_0240.map /.xfs		0		CX6V1201.xl	CX65/BOARD/SWAP/VDF
L36880-Q7100-A26	L36880-Q7100-A26	12 01 00	CX65_1_Standard_12_0001.map	CX65_2_xx-FFS-LG01_12_0240.map /.xfs	L55_NwSub-prepared_001.sim	16		CX651201.xl	CX65/BOARD/SWAP/SL16
L36880-Q7100-A80	L36880-Q7100-A80	12 08 00	CX6C_1_Standard_12_0001.map	CX6C_2_xx-FFS-LG08_12_0240.map /.xfs		0		CX6C1208.xl	CX65/BOARD/SWAP_A80
L36880-Q7100-A99	L36880-Q7100-A10	12 01 00	CX65_1_Standard_12_0001.map	CX65_2_xx-FFS-LG01_12_0240.map /.xfs		0		CX651201.xl	CX65/BOARD/SWAP
L36880-Q7100-C10	L36880-Q7100-C10	12 08 00	CX6C_1_Standard_12_0001.map	CX6C_2_xx-FFS-LG08_12_0240.map /.xfs		0		CX6C1208.xl	CX65/BOARD/SWAP_C10
L36880-Q7100-R10	L36880-Q7100-R10	12 08 00	CX6C_1_Standard_12_0001.map	CX6C_2_xx-FFS-LG08_12_0240.map /.xfs		0		CX6C1208.xl	CX65/BOARD/SWAP_R10
L36880-Q7100-S10	L36880-Q7100-S10	12 01 00	CX65_1_Standard_12_0001.map	CX65_2_xx-FFS-LG01_12_0240.map /.xfs		0		CX651201.xl	CX65/BOARD/SWAP_S10
S30880-S7100-A100		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG01_50_0409.map /.xfs		0		CX655001.xl	CX65/INT/RETAIL
S30880-S7100-A104		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_de-BRDHandel_50_0471.map /.xfs		0		CX655001.xl	CX65/DE/RETAIL/0
S30880-S7100-A106		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_it-RHQ5ME-final_50_0409.map /.xfs		0		CX655001.xl	CX65/SEM/RETAIL
S30880-S7100-A107		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_es-Amena_50_0471.map /.xfs	L55_Amena_001.sim	1		CX655001.xl	CX65/ES/AMENA
S30880-S7100-A108		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_ch-Sunrise_50_0471.map /.xfs		0		CX655001.xl	CX65/CH/SUNRISE
S30880-S7100-A109		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_va-LAM_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		CX655001.xl	CX65/LAM/RETAIL
S30880-S7100-A110		12 01 00	CX65_1_Standard_12_0001.map	CX65_2_de-o2-post_12_0251.map /.xfs		0		CX651201.xl	CX65/DE/O2-DE
S30880-S7100-A111		12 01 00	CX65_1_Standard_12_0001.map	CX65_2_uk-O2-Contract_12_0240.map /.xfs		0		CX651201.xl	CX65/UK/O2
S30880-S7100-A112		12 01 00	CX65_1_Standard_12_0001.map	CX65_2_uk-UKStandard_12_0240.map /.xfs		0		CX651201.xl	CX65/GB/RETAIL
S30880-S7100-A113		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_gr-retail-final_50_0409.map /.xfs		0		CX655001.xl	CX65/GB/Greece Retail
S30880-S7100-A115		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_pt-TMN-i9_50_0471.map /.xfs	L55_TMN_001.sim	1		CX655001.xl	CX65/PT/TMN/1
S30880-S7100-A116		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_es-Euskaltel_50_0471.map /.xfs	L55_Amena_001.sim	1		CX655001.xl	CX65/ES/EUSKALT/1
S30880-S7100-A117		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_es-Iberia_50_0409.map /.xfs		0		CX655001.xl	CX65/ES/IBERIA/0
S30880-S7100-A118		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_fr-Retail_50_0409.map /.xfs		0		CX655001.xl	CX65/FR/RETAIL/0
S30880-S7100-A119		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_de-BRDHandel_50_0471.map /.xfs	L55_E-Plus_001.sim	1		CX655001.xl	CX65/DE/EPLUS/1
S30880-S7100-A121		50 01 00	CX6V_1_Standard_50_0001.map	CX6V_2_de-VF-CX65V_50_0409.map /.xfs		0		CX6V5001.xl	CX65/DE/VDF/0
S30880-S7100-A124		47 01 00	CX65_1_Standard_47_0001.map	CX65_2_de-BRDHandel_47_0373.map /.xfs		0		CX654701.xl	CX65/DE/DAIMLER/0
S30880-S7100-A125		50 01 00	CX6V_1_Standard_50_0001.map	CX6V_2_pt-VF-StandardDesign_50_0409.map /.xfs	L55_Telecel_001.sim	1		CX6V5001.xl	CX65/PT/VDF/1
S30880-S7100-A130		15 01 00	CX6V_1_Standard_15_0001.map	CX6V_2_es-VF-StandardDesign_15_0285.map /.xfs	L55_Vodafone-Spain_001.sim	1		CX6V1501.xl	CX65V/ES/VF/1/MAINT-REL
S30880-S7100-A132		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_cl-EPCS_50_0409.map /.xfs	L55_Entel-Chile_002.sim	1		CX655001.xl	CX65/CL/ENTEL/1
S30880-S7100-A136		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_mx-Telcel_50_0409.map /.xfs	L55_Telcel_Mexico_001.sim	1		CX655001.xl	CX65/MX/TELCEL/1
S30880-S7100-A145		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_de-GFT-Jentro_50_0478.map /.xfs		0		CX655001.xl	CX65/DE/GFT/0
S30880-S7100-A200		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_dk-SWEFIN-Retail_50_0409.map /.xfs		0		CX655002.xl	CX65/FISE/RETAIL
S30880-S7100-A201		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_nc-Retail-NORDAN_50_0409.map /.xfs		0		CX655002.xl	CX65/NODE/RETAIL
S30880-S7100-A202		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_nc-Retail-NORDAN_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		CX655002.xl	CX65/NODE/PREPAID
S30880-S7100-A203		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_no-Telenor_50_0409.map /.xfs	L55_Telenor-Norway_001.sim	16		CX655002.xl	CX65/NO/TELENOR
S30880-S7100-A204		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_nl-Retail_50_0409.map /.xfs		0		CX655002.xl	CX65/NL/RETAIL/0
S30880-S7100-A208		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_sw-Telia-PostGo_50_0471.map /.xfs	L55_TeliaSweden_001.sim	1		CX655002.xl	CX65/SE/TELIA/1
S30880-S7100-A209		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_no-NetCom_50_0409.map /.xfs	L55_NetCom_003.sim	16		CX655002.xl	CX65/NO/NETCOM/1
S30880-S7100-A210		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_be-BERetail_50_0409.map /.xfs		0		CX655002.xl	CX65/BE/RETAIL/0
S30880-S7100-A211		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_dk-TDC-SPL_50_0409.map /.xfs	L55_TDC-Subset-Denmark_001.sim	16		CX655002.xl	CX65/DK/TDC/1
S30880-S7100-A212		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_sw-dk-CornvigGolive_50_0409.map /.xfs	L55_Cornvig-Sweden_001.sim	1		CX655002.xl	CX65/SE/COMVIQ/1
S30880-S7100-A214		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_nc-Retail-NORDAN_50_0409.map /.xfs	L55_Sonofon-noSP-Den_001.sim	16		CX655002.xl	CX65/DK/SONOFON
S30880-S7100-A215		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_uk-BTMobile-Corporate_50_0409.map /.xfs	L55_BTMobileUK_001.sim	2		CX655002.xl	CX65/GB/BT MOBI/0
S30880-S7100-A217		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG02_50_0409.map /.xfs		0		CX655002.xl	CX65/AE/RET_LG02/0
S30880-S7100-A303		50 03 00	CX65_1_Standard_50_0001.map	CX65_2_lt-Baltics_50_0409.map /.xfs		0		CX655003.xl	CX65/MIX/MULTI/0/BALTIC
S30880-S7100-A304		50 03 00	CX65_1_Standard_50_0001.map	CX65_2_ua-retail_50_0409.map /.xfs		0		CX655003.xl	CX65/UA/RETAIL/0
S30880-S7100-A305		50 03 00	CX65_1_Standard_50_0001.map	CX65_2_lt-Baltics_50_0409.map /.xfs	L55_Baltics-prepared_Simlock_001.sim	1		CX655003.xl	CX65/LTLV/RETAI/1/FLASH

Mastertabelle

Produkt

Datei

Name

BOM-95876-80-000

CX65

BOM-95876-80-000

Sparka

Funkgerät	Swap-Baugruppe	SW LG TG	Standard-I	Kunden-I	SIM-Lock	Level	Tegic	Sprache	Gerätevariante
S30880-S7100-A306		50 03 00	CX65_1_Standard_50_0001.map	CX65_2_ee-emrtele2_50_0409.map /.xfs		0		CX655003.xl	CX65/EE/RETAIL/0
S30880-S7100-A307		50 03 00	CX65_1_Standard_50_0001.map	CX65_2 lt-Baltics_50_0409.map /.xfs	L55_Baltics-prepared_Simlock_001.sim	1		CX655003.xl	CX65/LTLV/RETAIL/1
S30880-S7100-A390		50 03 00	CX65_1_Standard_50_0001.map	CX65_2_ru-RussianRetail_50_0409.map /.xfs		0		CX655003.xl	CX65/RU/RETAIL/0
S30880-S7100-A391		50 92 00	CX65_1_Standard_50_0001.map	CX65_2_ru-RussianRetail_50_0409.map /.xfs		0		CX655092.xl	CX65/RU/RETAIL/0
S30880-S7100-A402		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_hu-Pannon_50_0471.map /.xfs		0		CX655004.xl	CX65/HU/PANNON_D/0
S30880-S7100-A403		50 04 00	CX65_1_Standard_50_0001.map	CX65_2 at-Telering_50_0471.map /.xfs	L55_Telering_001.sim	1		CX655004.xl	CX65/AT/TELERIN/1
S30880-S7100-A404		50 04 00	CX65_1_Standard_50_0001.map	CX65_2 at-OneConnect_50_0471.map /.xfs	L55_one connect_001.sim	1		CX655004.xl	CX65/AT/ONECONN/1
S30880-S7100-A405		50 04 00	CX65_1_Standard_50_0001.map	CX65_2 pl-Centertel_50_0409.map /.xfs	L55_Centertel-POL_001.sim	1		CX655004.xl	CX65/PL/BG-CENTERT/1/HEADSET
S30880-S7100-A406		50 04 00	CX65_1_Standard_50_0001.map	CX65_2 pl-Polkomtel_50_0409.map /.xfs	L55_POLKOMTEL_001.sim	1		CX655004.xl	CX65/PL/POLKOMT/1
S30880-S7100-A407		16 04 00	CX65_1_Standard_16_0001.map	CX65_2 hr-HTmobile_16_0274.map /.xfs	L55_Cronet_001.sim	1		CX651604.xl	CX65/HR/HTMOBIL/1
S30880-S7100-A408		50 04 00	CX65_1_Standard_50_0001.map	CX65_2 xx-FFS-LG04_50_0409.map /.xfs		0		CX655004.xl	CX65/CZ/RETAIL/0
S30880-S7100-A409		50 04 00	CX65_1_Standard_50_0001.map	CX65_2 cz-Eurotel_50_0409.map /.xfs	L55_Eurotel_Czech_001.sim	1		CX655004.xl	CX65/CZ/EUROTET/1
S30880-S7100-A410		50 04 00	CX65_1_Standard_50_0001.map	CX65_2 si-Slovenia-mobitel_50_0471.map /.xfs	L55_Mobitel_001.sim	1		CX655004.xl	CX65/SI/MOBITEL/1
S30880-S7100-A412		50 04 00	CX65_1_Standard_50_0001.map	CX65_2 pl-PTC_50_0409.map /.xfs	L55_PTC-POL_001.sim	1		CX655004.xl	CX65/PL/PTC_ERA/1
S30880-S7100-A413		50 04 00	CX65_1_Standard_50_0001.map	CX65_2 si-Slovenia-debitel_50_0471.map /.xfs		0		CX655004.xl	CX65/SI/DEBITEL/0
S30880-S7100-A414		50 04 00	CX65_1_Standard_50_0001.map	CX65_2 hr-RetailVariant_50_0409.map /.xfs		0		CX655004.xl	CX65/HR/RETAIL/0
S30880-S7100-A420		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_hu-Pannon-neutral_50_0471.map /.xfs	L55_Pannon-Hungary_001.sim	1		CX655004.xl	CX65/HU/PANNON/1
S30880-S7100-A501		50 05 00	CX65_1_Standard_50_0001.map	CX65_2 xx-FFS-LG05_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		CX655005.xl	CX65/RO/BG-RETAIL/1
S30880-S7100-A502		50 05 00	CX65_1_Standard_50_0001.map	CX65_2 ro-orange_50_0421.map /.xfs	L55_Orange-Romania_001.sim	1		CX655005.xl	CX65/RO/ORANGE/1
S30880-S7100-A600		50 06 00	CX65_1_Standard_50_0001.map	CX65_2 ae-MiddleEast-Retail_50_0409.map /.xfs		0		CX655006.xl	CX65/ME/RETAIL
S30880-S7100-A601		50 06 00	CX65_1_Standard_50_0001.map	CX65_2 za-Africa-Retail_50_0409.map /.xfs		0		CX655006.xl	CX65/AFR/RETAIL/0
S30880-S7100-A602		50 06 00	CX65_1_Standard_50_0001.map	CX65_2_ma-MarocTelecom-IAMPostPaid_50_0409.map /.xfs		0		CX655006.xl	CX65/MA/MOROCCO/0
S30880-S7100-A603		50 06 00	CX65_1_Standard_50_0001.map	CX65_2 ae-MiddleEast-Retail_50_0409.map /.xfs		0		CX655006.xl	CX65/AE/ME-RET./0
S30880-S7100-A700		50 07 00	CX65_1_Standard_50_0001.map	CX65_2 ap-APAC-Int_50_0409.map /.xfs		0		CX655007.xl	CX65/INT/APAC
S30880-S7100-A701		50 07 00	CX65_1_Standard_50_0001.map	CX65_2 th-Thai-S_50_0409.map /.xfs		0		CX655007.xl	CX65/TH/RETAIL
S30880-S7100-A702		50 07 00	CX65_1_Standard_50_0001.map	CX65_2_au-AustraliaNZ-RETAIL_50_0409.map /.xfs		0		CX655007.xl	CX65/AU/RETAIL/0
S30880-S7100-A801		50 08 00	CX6C_1_Standard_50_0001.map	CX6C_2 tw-Taiwan_50_0409.map /.xfs		0		CX6C5008.xl	CX65/TW/RETAIL
S30880-S7100-A802		50 08 00	CX6C_1_Standard_50_0001.map	CX6C_2 hk-HSM-delta_50_0409.map /.xfs		0		CX6C5008.xl	CX65/HSM
S30880-S7100-B100		43 01 00	CX65_1_Standard_43_0001.map	CX65_2 uk-Orange_43_0363.map /.xfs	L55_OrangeUK_001.sim	1		CX654301.xl	CX65/UK/ORANGE/1
S30880-S7100-B101		43 01 00	CX65_1_Standard_43_0001.map	CX65_2 fr-Orange_43_0363.map /.xfs	L55_Orange-France_002.sim	1		CX654301.xl	CX65/FR/ORANGE/1
S30880-S7100-B102		14 01 00	CX65_1_Standard_14_0001.map	CX65_2 ch-Orange_14_0250.map /.xfs		0		CX651401.xl	CX65/CH/ORANGE/0
S30880-S7100-B400		16 04 00	CX65_1_Standard_16_0001.map	CX65_2 sk-orange_16_0266.map /.xfs		0		CX651604.xl	CX65/SK/ORANGE/0
S30880-S7100-D129		43 01 00	CX65_1_Standard_43_0001.map	CX65_2 xx-FFS-LG01_43_0363.map /.xfs		0		CX654301.xl	CX65/TRL/AT/SIEM/0/LE
S30880-S7100-D143		50 01 00	CX65_1_Standard_50_0001.map	CX65_2 de-Ronaldo-LE_50_0430.map /.xfs		0		CX655001.xl	CX65/RONALDO/INT/LE/0
S30880-S7100-G100		50 01 00	CX65_1_Standard_50_0001.map	CX65_2 xx-FFS-LG01_50_0409.map /.xfs		0		CX655001.xl	CX65/INT/RETAIL
S30880-S7100-G104		50 01 00	CX65_1_Standard_50_0001.map	CX65_2 de-BRDHandel_50_0471.map /.xfs		0		CX655001.xl	CX65/DE/RETAIL/0
S30880-S7100-G106		50 01 00	CX65_1_Standard_50_0001.map	CX65_2 it-RHQSM-final_50_0409.map /.xfs		0		CX655001.xl	CX65/SEM/RETAIL
S30880-S7100-G107		50 01 00	CX65_1_Standard_50_0001.map	CX65_2 es-Amena_50_0471.map /.xfs	L55_Amena_001.sim	1		CX655001.xl	CX65/ES/AMENA
S30880-S7100-G109		50 01 00	CX65_1_Standard_50_0001.map	CX65_2 va-LAM_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		CX655001.xl	CX65/LAM/RETAIL
S30880-S7100-G110		12 01 00	CX65_1_Standard_12_0001.map	CX65_2 de-o2-post_12_0251.map /.xfs		0		CX651201.xl	CX65/DE/O2-DE
S30880-S7100-G121		50 01 00	CX6V_1_Standard_50_0001.map	CX6V_2 de-VF-CX65V_50_0409.map /.xfs		0		CX6V5001.xl	CX65/DE/VDF/0
S30880-S7100-G124		47 01 00	CX65_1_Standard_47_0001.map	CX65_2 de-BRDHandel_47_0373.map /.xfs		0		CX654701.xl	CX65/DE/DAIMLER/0
S30880-S7100-G125		50 01 00	CX6V_1_Standard_50_0001.map	CX6V_2_pt-VF-StandardDesign_50_0409.map /.xfs	L55_Telecel_001.sim	1		CX6V5001.xl	CX65/PT/VDF/1
S30880-S7100-G130		15 01 00	CX6V_1_Standard_15_0001.map	CX6V_2_es-VF-StandardDesign_15_0285.map /.xfs	L55_Vodafone-Spain_001.sim	1		CX6V1501.xl	CX65/VES/VF/1/MAINT-REL
S30880-S7100-G390		50 03 00	CX65_1_Standard_50_0001.map	CX65_2_ru-RussianRetail_50_0409.map /.xfs		0		CX655003.xl	CX65/RU/RETAIL/0
S30880-S7100-G400		16 04 00	CX65_1_Standard_16_0001.map	CX65_2 sk-orange_16_0266.map /.xfs		0		CX651604.xl	CX65/SK/ORANGE/0
S30880-S7100-H100		14 01 00	CX65_1_Standard_14_0001.map	CX65_2 uk-Orange_14_0250.map /.xfs	L55_OrangeUK_001.sim	1		CX651401.xl	CX65/UK/ORANGE/1
S30880-S7100-H101		43 01 00	CX65_1_Standard_43_0001.map	CX65_2 fr-Orange_43_0363.map /.xfs	L55_Orange-France_002.sim	1		CX654301.xl	CX65/FR/ORANGE/1
S30880-S7100-M100		50 01 00	CX65_1_Standard_50_0001.map	CX65_2 xx-FFS-LG01_50_0409.map /.xfs		0		CX655001.xl	CX65/INT/RETAIL
S30880-S7100-M109		50 01 00	CX65_1_Standard_50_0001.map	CX65_2 va-LAM_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		CX655001.xl	CX65/LAM/RETAIL
S30880-S7100-M122		50 01 00	CX65_1_Standard_50_0001.map	CX65_2 br-TIM_50_0409.map /.xfs	L55_TIM-Brazil_001.sim	1		CX655001.xl	CX65/BR/TIM/1
S30880-S7100-M127		50 01 00	CX65_1_Standard_50_0001.map	CX65_2 br-Oi_50_0409.map /.xfs	L55_Oi_Teleamar_001.sim	1		CX655001.xl	CX65/BR/OI/1
S30880-S7100-M128		50 01 00	CX65_1_Standard_50_0001.map		L55_Brasil-Telecom_001.sim	1		CX655001.xl	CX65/BR/TELECOM/1
S30880-S7100-M132		50 01 00	CX65_1_Standard_50_0001.map	CX65_2 cl-EPCS_50_0409.map /.xfs	L55_Entel-Chile_002.sim	1		CX655001.xl	CX65/CL/ENTEL/1
S30880-S7100-M134		50 01 00	CX65_1_Standard_50_0001.map	CX65_2 br-Retail_50_0409.map /.xfs		0		CX655001.xl	CX65/BR/RETAIL/0
S30880-S7100-M136		50 01 00	CX65_1_Standard_50_0001.map	CX65_2 mx-Telcel_50_0409.map /.xfs	L55_Telcel_Mexico_001.sim	1		CX655001.xl	CX65/MX/TELCEL/1

Mastertabelle

Produkt

Datei

Name

BOM-95876-80-000

CX65

BOM-95876-80-000

Sparka

Funkgerät	Swap-Baugruppe	SW LG TG	Standard-I	Kunden-I	SIM-Lock	Level	Tegic	Sprache	Gerätevariante
S30880-S7100-M137		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_br-Amazonia_50_0409.map /.xfs	L55_Amazonia-Brasil_001.sim	1		CX655001.xl	CX65/BR/AMAZONIA/1
S30880-S7100-M138		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_br-TelemigCelular_50_0409.map /.xfs		0		CX655001.xl	CX65/BR/TELEMIG/0
S30880-S7100-M141		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_br-TIM-BroaSpecialEdition_50_0410.map /.xfs	L55_TIM-Brazil_001.sim	1		CX655001.xl	CX65/CS/BR/TIM/BROA/1
S30880-S7100-S100		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG01_50_0409.map /.xfs		0		CX655001.xl	CX65/INT/RETAIL
S30880-S7100-S104		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_de-BRDHandel_50_0471.map /.xfs		0		CX655001.xl	CX65/DE/RETAIL/0
S30880-S7100-S106		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_it-RHQSM-final_50_0409.map /.xfs		0		CX655001.xl	CX65/SEM/RETAIL
S30880-S7100-S107		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_es-Amena_50_0471.map /.xfs	L55_Amena_001.sim	1		CX655001.xl	CX65/ES/AMENA
S30880-S7100-S108		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_ch-Sunrise_50_0471.map /.xfs		0		CX655001.xl	CX65/CH/SUNRISE
S30880-S7100-S109		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_va-LAM_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		CX655001.xl	CX65/LAM/RETAIL
S30880-S7100-S110		12 01 00	CX65_1_Standard_12_0001.map	CX65_2_de-o2-post_12_0251.map /.xfs		0		CX651201.xl	CX65/DE/O2-DE
S30880-S7100-S115		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_pt-TMN-i9_50_0471.map /.xfs	L55_TMN_001.sim	1		CX655001.xl	CX65/PT/TMN/1
S30880-S7100-S116		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_es-Euskaltel_50_0471.map /.xfs	L55_Amena_001.sim	1		CX655001.xl	CX65/ES/EUSKALT/1
S30880-S7100-S117		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_es-Iberia_50_0409.map /.xfs		0		CX655001.xl	CX65/ES/IBERIA/0
S30880-S7100-S118		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_fr-Retail_50_0409.map /.xfs		0		CX655001.xl	CX65/FR/RETAIL/0
S30880-S7100-S121		50 01 00	CX6V_1_Standard_50_0001.map	CX6V_2_de-VF-CX65V_50_0409.map /.xfs		0		CX6V5001.xl	CX65/DE/VDF/0
S30880-S7100-S136		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_mx-Telcel_50_0409.map /.xfs	L55_Telcel_Mexico_001.sim	1		CX655001.xl	CX65/MX/TELCEL/1
S30880-S7100-S145		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_de-GFT-Jentro_50_0478.map /.xfs		0		CX655001.xl	CX65/DE/GFT/0
S30880-S7100-S200		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_dk-SWEFIN-Retail_50_0409.map /.xfs		0		CX655002.xl	CX65/FISE/RETAIL
S30880-S7100-S201		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_nc-Retail-NORDAN_50_0409.map /.xfs		0		CX655002.xl	CX65/NODE/RETAIL
S30880-S7100-S202		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_nc-Retail-NORDAN_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		CX655002.xl	CX65/NODE/PREPAID
S30880-S7100-S203		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_no-Telenor_50_0409.map /.xfs	L55_Telenor-Norway_001.sim	16		CX655002.xl	CX65/NO/TELENOR
S30880-S7100-S204		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_nl-Retail_50_0409.map /.xfs		0		CX655002.xl	CX65/NL/RETAIL/0
S30880-S7100-S208		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_sw-Telia-PostGo_50_0471.map /.xfs	L55_TeliaSweden_001.sim	1		CX655002.xl	CX65/SE/TELIA/1
S30880-S7100-S209		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_no-NetCom_50_0409.map /.xfs	L55_NetCom_003.sim	16		CX655002.xl	CX65/NO/NETCOM/1
S30880-S7100-S210		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_be-BERetail_50_0409.map /.xfs		0		CX655002.xl	CX65/BE/RETAIL/0
S30880-S7100-S212		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_sw-dk-ComviqGolive_50_0409.map /.xfs	L55_Comviq-Sweden_001.sim	1		CX655002.xl	CX65/SE/COMVIQ/1
S30880-S7100-S303		50 03 00	CX65_1_Standard_50_0001.map	CX65_2_it-Baltics_50_0409.map /.xfs		0		CX655003.xl	CX65/MIX/MULTI/0/BALTIC
S30880-S7100-S304		50 03 00	CX65_1_Standard_50_0001.map	CX65_2_ua-retail_50_0409.map /.xfs		0		CX655003.xl	CX65/UA/RETAIL/0
S30880-S7100-S390		50 03 00	CX65_1_Standard_50_0001.map	CX65_2_ru-RussianRetail_50_0409.map /.xfs		0		CX655003.xl	CX65/RU/RETAIL/0
S30880-S7100-S402		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_hu-Pannon_50_0471.map /.xfs		0		CX655004.xl	CX65/HU/PANNON_D/0
S30880-S7100-S403		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_at-Telering_50_0471.map /.xfs	L55_Telering_001.sim	1		CX655004.xl	CX65/AT/TELERIN/1
S30880-S7100-S405		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_pl-Centertel_50_0409.map /.xfs	L55_Centertel-POL_001.sim	1		CX655004.xl	CX65/PL/CENTERT/1/HEADSET
S30880-S7100-S406		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_pl-Polkomtel_50_0409.map /.xfs	L55_POLKOMTEL_001.sim	1		CX655004.xl	CX65/PL/POLKOMT/1
S30880-S7100-S407		16 04 00	CX65_1_Standard_16_0001.map	CX65_2_hr-HTmobile_16_0274.map /.xfs	L55_Cronet_001.sim	1		CX651604.xl	CX65/HR/HTMOBIL/1
S30880-S7100-S408		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG04_50_0409.map /.xfs		0		CX655004.xl	CX65/CZ/RETAIL/0
S30880-S7100-S409		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_cz-Eurotel_50_0409.map /.xfs	L55_Eurotel Czech_001.sim	1		CX655004.xl	CX65/CZ/EUROTTEL/1
S30880-S7100-S410		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_si-Slovenia-mobitel_50_0471.map /.xfs	L55_Mobitel_001.sim	1		CX655004.xl	CX65/SI/MOBITEL/1
S30880-S7100-S412		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_pl-PTC_50_0409.map /.xfs	L55_PTC-POL_001.sim	1		CX655004.xl	CX65/PL/PTC_ERA/1
S30880-S7100-S501		50 05 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG05_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		CX655005.xl	CX65/RO/BG-RETAIL/1
S30880-S7100-S600		50 06 00	CX65_1_Standard_50_0001.map	CX65_2_ae-MiddleEast-Retail_50_0409.map /.xfs		0		CX655006.xl	CX65/ME/RETAIL
S30880-S7100-S601		50 06 00	CX65_1_Standard_50_0001.map	CX65_2_za-Africa-Retail_50_0409.map /.xfs		0		CX655006.xl	CX65/AFR/RETAIL/0
S30880-S7100-S700		50 07 00	CX65_1_Standard_50_0001.map	CX65_2_ap-APAC-Int_50_0409.map /.xfs		0		CX655007.xl	CX65/INT/APAC
S30880-S7100-S701		50 07 00	CX65_1_Standard_50_0001.map	CX65_2_th-Thai-S_50_0409.map /.xfs		0		CX655007.xl	CX65/TH/RETAIL
S30880-S7100-S702		50 07 00	CX65_1_Standard_50_0001.map	CX65_2_au-AustraliaNZ-RETAIL_50_0409.map /.xfs		0		CX655007.xl	CX65/AU/RETAIL/0
S30880-S7100-S800		25 08 00	CX6C_1_Standard_25_0001.map	CX6C_2_cn-ChinaRetail_25_0304.map /.xfs		0		CX6C2508.xl	CX65/INT/CHINA
S30880-S7100-S802		50 08 00	CX6C_1_Standard_50_0001.map	CX6C_2_hk-HSM-delta_50_0409.map /.xfs		0		CX6C5008.xl	CX65/HSM
S30880-S7100-U100		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG01_50_0409.map /.xfs		0		CX655001.xl	CX65/INT/RETAIL
S30880-S7100-U104		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_de-BRDHandel_50_0471.map /.xfs		0		CX655001.xl	CX65/DE/RETAIL/0
S30880-S7100-U106		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_it-RHQSM-final_50_0409.map /.xfs		0		CX655001.xl	CX65/SEM/RETAIL
S30880-S7100-U107		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_es-Amena_50_0471.map /.xfs	L55_Amena_001.sim	1		CX655001.xl	CX65/ES/AMENA
S30880-S7100-U108		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_ch-Sunrise_50_0471.map /.xfs		0		CX655001.xl	CX65/CH/SUNRISE
S30880-S7100-U109		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_va-LAM_50_0409.map /.xfs	L55_Nw-prepared_001.sim	1		CX655001.xl	CX65/LAM/RETAIL
S30880-S7100-U110		12 01 00	CX65_1_Standard_12_0001.map	CX65_2_de-o2-post_12_0251.map /.xfs		0		CX651201.xl	CX65/DE/O2-DE
S30880-S7100-U115		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_pt-TMN-i9_50_0471.map /.xfs	L55_TMN_001.sim	1		CX655001.xl	CX65/PT/TMN/1
S30880-S7100-U116		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_es-Euskaltel_50_0471.map /.xfs	L55_Amena_001.sim	1		CX655001.xl	CX65/ES/EUSKALT/1
S30880-S7100-U117		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_es-Iberia_50_0409.map /.xfs		0		CX655001.xl	CX65/ES/IBERIA/0
S30880-S7100-U118		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_fr-Retail_50_0409.map /.xfs		0		CX655001.xl	CX65/FR/RETAIL/0
S30880-S7100-U121		50 01 00	CX6V_1_Standard_50_0001.map	CX6V_2_de-VF-CX65V_50_0409.map /.xfs		0		CX6V5001.xl	CX65/DE/VDF/0

Mastertabelle

Produkt

Datei

Name

BOM-95876-80-000

CX65

BOM-95876-80-000

Sparka

Funkgerät	Swap-Baugruppe	SW LG TG	Standard-I	Kunden-I	SIM-Lock	Level	Tegic	Sprache	Gerätevariante
S30880-S7100-U136		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_mx-Telcel_50_0409.map /.xls	L55_Telcel_Mexico_001.sim	1		CX655001.xl	CX65/MX/TELCEL/1
S30880-S7100-U200		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_dk-SWEFIN-Retail_50_0409.map /.xls		0		CX655002.xl	CX65/FISE/RETAIL
S30880-S7100-U201		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_nc-Retail-NORDAN_50_0409.map /.xls		0		CX655002.xl	CX65/NODE/RETAIL
S30880-S7100-U202		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_nc-Retail-NORDAN_50_0409.map /.xls	L55_Nw-prepared_001.sim	1		CX655002.xl	CX65/NODE/PREPAID
S30880-S7100-U203		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_no-Telenor_50_0409.map /.xls	L55_Telenor-Norway_001.sim	16		CX655002.xl	CX65/NO/TELENOR
S30880-S7100-U204		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_nl-Retail_50_0409.map /.xls		0		CX655002.xl	CX65/NL/RETAIL/0
S30880-S7100-U208		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_sw-Telia-PostGo_50_0471.map /.xls	L55_TeliaSweden_001.sim	1		CX655002.xl	CX65/SE/TELIA/1
S30880-S7100-U209		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_no-NetCom_50_0409.map /.xls	L55_NetCom_003.sim	16		CX655002.xl	CX65/NO/NETCOM/1
S30880-S7100-U210		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_be-BERetail_50_0409.map /.xls		0		CX655002.xl	CX65/BE/RETAIL/0
S30880-S7100-U212		50 02 00	CX65_1_Standard_50_0001.map	CX65_2_sw-dk-CorviiqGolive_50_0409.map /.xls	L55_Corviiq-Sweden_001.sim	1		CX655002.xl	CX65/SE/COMVIQ/1
S30880-S7100-U303		50 03 00	CX65_1_Standard_50_0001.map	CX65_2_lt-Baltics_50_0409.map /.xls		0		CX655003.xl	CX65/MIX/MULTI/0/BALTIC
S30880-S7100-U304		50 03 00	CX65_1_Standard_50_0001.map	CX65_2_ua-retail_50_0409.map /.xls		0		CX655003.xl	CX65/UA/RETAIL/0
S30880-S7100-U390		50 03 00	CX65_1_Standard_50_0001.map	CX65_2_ru-RussianRetail_50_0409.map /.xls		0		CX655003.xl	CX65/RU/RETAIL/0
S30880-S7100-U391		50 92 00	CX65_1_Standard_50_0001.map	CX65_2_ru-RussianRetail_50_0409.map /.xls		0		CX655092.xl	CX65/RU/RETAIL/0
S30880-S7100-U402		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_hu-Pannon_50_0471.map /.xls		0		CX655004.xl	CX65/HU/PANNON D/0
S30880-S7100-U403		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_at-Telering_50_0471.map /.xls	L55_Telering_001.sim	1		CX655004.xl	CX65/AT/TELERIN/1
S30880-S7100-U405		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_pl-Centertel_50_0409.map /.xls	L55_Centertel-POL_001.sim	1		CX655004.xl	CX65/PL/CENTERT/1/HEADSET
S30880-S7100-U406		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_pl-Polkomtel_50_0409.map /.xls	L55_POLKOMTEL_001.sim	1		CX655004.xl	CX65/PL/POLKOMT/1
S30880-S7100-U407		16 04 00	CX65_1_Standard_16_0001.map	CX65_2_hr-HTmobile_16_0274.map /.xls	L55_Cronet_001.sim	1		CX651604.xl	CX65/HR/HTMOBIL/1
S30880-S7100-U408		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG04_50_0409.map /.xls		0		CX655004.xl	CX65/CZ/RETAIL/0
S30880-S7100-U409		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_cz-Eurotel_50_0409.map /.xls	L55_Eurotel Czech_001.sim	1		CX655004.xl	CX65/MIX/EUROT/1
S30880-S7100-U410		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_si-Slovenia-mobitel_50_0471.map /.xls	L55_Mobitel_001.sim	1		CX655004.xl	CX65/SI/MOBITEL/1
S30880-S7100-U412		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_pl-PTC_50_0409.map /.xls	L55_PTC-POL_001.sim	1		CX655004.xl	CX65/PL/PTC_ERA/1
S30880-S7100-U501		50 05 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG05_50_0409.map /.xls	L55_Nw-prepared_001.sim	1		CX655005.xl	CX65/RO/BG-RETAIL/1
S30880-S7100-U600		50 06 00	CX65_1_Standard_50_0001.map	CX65_2_ae-MiddleEast-Retail_50_0409.map /.xls		0		CX655006.xl	CX65/ME/RETAIL
S30880-S7100-U601		50 06 00	CX65_1_Standard_50_0001.map	CX65_2_za-Africa-Retail_50_0409.map /.xls		0		CX655006.xl	CX65/AFR/RETAIL/0
S30880-S7100-Z400		16 04 00	CX65_1_Standard_16_0001.map	CX65_2_sk-orange_16_0266.map /.xls		0		CX651604.xl	CX65/SK/ORANGE/0
S30880-S7110-A100		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG01_50_0409.map /.xls		0		CX655001.xl	CXV65/INT/RETAIL
S30880-S7110-A600		43 06 00	CX65_1_Standard_43_0001.map	CX65_2_ae-MiddleEast-CXV65Retail_43_0374.m ap /.xls		0		CX654306.xl	CXV65/GS/AE/RETAIL/0/MIDDLEEAST
S30880-S7110-B105		12 01 00	CX6V_1_Standard_12_0001.map	CX6V_2_gr-VF_12_0240.map /.xls		0		CX6V1201.xl	CXV65/GR/VDF/0
S30880-S7110-B111		12 01 00	CX6V_1_Standard_12_0001.map	CX6V_2_nz-VF_12_0240.map /.xls		0		CX6V1201.xl	CXV65/NZ/VDF/0
S30880-S7110-B112		12 01 00	CX6V_1_Standard_12_0001.map	CX6V_2_ie-VF-Post_12_0240.map /.xls	L55_Vodafone-IRE_001.sim	1		CX6V1201.xl	CXV65/IE/VDF/1
S30880-S7110-B201		15 02 00	CX6V_1_Standard_15_0001.map	CX6V_2_nl-VF_15_0256.map /.xls	L55_Vodafone-NL_001.sim	1		CX6V1502.xl	CXV65/NL/VDF/1
S30880-S7110-B202		12 02 00	CX6V_1_Standard_12_0001.map	CX6V_2_be-Proximus_12_0247.map /.xls		0		CX6V1202.xl	CXV65/BE/PROXIM/0
S30880-S7110-B204		12 02 00	CX6V_1_Standard_12_0001.map	CX6V_2_ie-VF-Post_12_0240.map /.xls	L55_Vodafone-IRE_001.sim	1		CX6V1202.xl	CXV65/IE/VDF/1
S30880-S7110-B400		12 04 00	CX6V_1_Standard_12_0001.map	CX6V_2_hu-VF_12_0240.map /.xls	L55_Vodafone-Hungary_001.sim	1		CX6V1204.xl	CXV65/HU/VDF/1
S30880-S7110-B403		12 04 00	CX6V_1_Standard_12_0001.map	CX6V_2_hr-VF-VIPnet_12_0240.map /.xls	L55_Vipnet Croatia_001.sim	1		CX6V1204.xl	CXV65/HR/VIPNET/1
S30880-S7110-B600		12 06 00	CX6V_1_Standard_12_0001.map	CX6V_2_eg-VF_12_0240.map /.xls		0		CX6V1206.xl	CXV65/EG/VDF/0
S30880-S7110-S800		25 08 00	CX6C_1_Standard_25_0001.map	CX6C_2_cn-ChinaRetail-CXV_25_0304.map /.xls		0		CX6C2508.xl	CXV65/INT/CHINA
S30880-S7110-W111		12 01 00	CX6V_1_Standard_12_0001.map	CX6V_2_nz-VF_12_0240.map /.xls		0		CX6V1201.xl	CXV65/NZ/VDF/0
S30880-S7120-A100		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG01_50_0409.map /.xls		0		CX655001.xl	CXT65/INT/RETAIL
S30880-S7120-A101		12 01 00	CX65_1_Standard_12_0001.map	CX65_2_it-TIM-preliminary_12_0240.map /.xls		0		CX651201.xl	CXT65/IT/TIM
S30880-S7120-A102		16 01 00	CX65_1_Standard_16_0001.map	CX65_2_es-Movistar-post_16_0266.map /.xls	L55_Telefonica-Movistar_001.sim	1		CX651601.xl	CXT65/ES/TELEF/1
S30880-S7120-A103		25 01 00	CX6V_1_Standard_25_0001.map	CX6V_2_fr-VF-SFR_25_0300.map /.xls	L55_SFR-France_001.sim	1		CX6V2501.xl	CXT65/FR/SFR/VF/1/CX6V-SW
S30880-S7120-A107		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_uk-Retail-WorldPhone_50_0471.map /.xls		0		CX655001.xl	CXT65/SS/AFRI/WP/0
S30880-S7120-A108		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_cl-EPCS_50_0409.map /.xls	L55_Entel-Chile_002.sim	1		CX655001.xl	CXT65/CL/EPCS/1
S30880-S7120-A402		43 04 00	CX65_1_Standard_43_0001.map	CX65_2_sk-EuroTel_43_0363.map /.xls	L55_Eurotel Slovakia_001.sim	1		CX654304.xl	CXT65/SK/EUROT/EL
S30880-S7120-A403		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_pl-PTC_50_0409.map /.xls	L55_PTC-POL_001.sim	1		CX655004.xl	CXT65/PL/ERA/1
S30880-S7120-A600		50 06 00	CX65_1_Standard_50_0001.map	CX65_2_uk-Retail-WorldPhone_50_0435.map /.xls		0		CX655006.xl	CXT65/SS/AFR/WORLDPHONE/0
S30880-S7120-A700		50 07 00	CX65_1_Standard_50_0001.map	CX65_2_ap-APACInt-CXT_50_0441.map /.xls		0		CX655007.xl	CXT65/INT/APAC
S30880-S7120-B100		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG01_50_0471.map /.xls		0		CX655001.xl	CXT65/INT/TMO
S30880-S7120-B400		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_cz-T-Mobile_50_0471.map /.xls		0		CX655004.xl	CXT65/CZ/TMO
S30880-S7120-B401		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_at-T-Mobile_50_0471.map /.xls	L55_Maxmobil_002.sim	1		CX655004.xl	CXT65/AT/TMO
S30880-S7120-B402		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_de-T-Mobile_50_0471.map /.xls		0		CX655004.xl	CXT65/DE/TMO
S30880-S7120-B403		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_uk-T-Mobile_50_0471.map /.xls	L55_T-Mobile-UK_002.sim	1		CX655004.xl	CXT65/GB/TMO
S30880-S7120-B404		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_nl-T-Mobile_50_0471.map /.xls	L55_BEN_001.sim	1		CX655004.xl	CXT65/NL/TMO
S30880-S7120-B405		25 04 00	CX65_1_Standard_25_0001.map	CX65_2_hu-T-Mobile_25_0304.map /.xls	L55_Westel-Hungary_001.sim	1		CX652504.xl	CXT65/HU/WESTEL/1

Funkgerät	Swap-Baugruppe	SW LG TG	Standard-I	Kunden-I	SIM-Lock	Level	Tegic	Sprache	Gerätevariante
S30880-S7120-G102		16 01 00	CX65_1_Standard_16_0001.map	CX65_2_es-Movistar-post_16_0266.map /.xfs	L55_Telefonica-Movistar_001.sim	1		CX651601.xl	CXT65/ES/TELEF/1
S30880-S7120-G103		25 01 00	CX6V_1_Standard_25_0001.map	CX6V_2_fr-VF-SFR_25_0300.map /.xfs	L55_SFR-France_001.sim	1		CX6V2501.xl	CXT65/FR/SFR/VF/1/CX6V-SW
S30880-S7120-M106		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_br-TIM_50_0409.map /.xfs	L55_TIM-Brazil_001.sim	1		CX655001.xl	CXT65/SS/BR/TIM/1
S30880-S7120-M108		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_cl-EPCS_50_0409.map /.xfs	L55_Entel-Chile_002.sim	1		CX655001.xl	CXT65/CL/EPCS/1
S30880-S7120-S100		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG01_50_0409.map /.xfs		0		CX655001.xl	CXT65/INT/RETAIL
S30880-S7120-S102		16 01 00	CX65_1_Standard_16_0001.map	CX65_2_es-Movistar-post_16_0266.map /.xfs	L55_Telefonica-Movistar_001.sim	1		CX651601.xl	CXT65/ES/TELEF/1
S30880-S7120-S103		25 01 00	CX6V_1_Standard_25_0001.map	CX6V_2_fr-VF-SFR_25_0300.map /.xfs	L55_SFR-France_001.sim	1		CX6V2501.xl	CXT65/FR/SFR/VF/1/CX6V-SW
S30880-S7120-S402		43 04 00	CX65_1_Standard_43_0001.map	CX65_2_sk-EuroTel_43_0363.map /.xfs	L55_Eurotel_Slovakia_001.sim	1		CX654304.xl	CXT65/SK/EUROTTEL
S30880-S7120-S403		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_pl-PTC_50_0409.map /.xfs	L55_PTC-POL_001.sim	1		CX655004.xl	CXT65/PL/ERA/1
S30880-S7120-S700		50 07 00	CX65_1_Standard_50_0001.map	CX65_2_ap-APACInt-CXT_50_0441.map /.xfs		0		CX655007.xl	CXT65/INT/APAC
S30880-S7120-U100		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG01_50_0409.map /.xfs		0		CX655001.xl	CXT65/INT/RETAIL
S30880-S7120-U102		16 01 00	CX65_1_Standard_16_0001.map	CX65_2_es-Movistar-post_16_0266.map /.xfs	L55_Telefonica-Movistar_001.sim	1		CX651601.xl	CXT65/ES/TELEF/1
S30880-S7120-U103		25 01 00	CX6V_1_Standard_25_0001.map	CX6V_2_fr-VF-SFR_25_0300.map /.xfs	L55_SFR-France_001.sim	1		CX6V2501.xl	CXT65/FR/SFR/VF/1/CX6V-SW
S30880-S7120-U402		43 04 00	CX65_1_Standard_43_0001.map	CX65_2_sk-EuroTel_43_0363.map /.xfs	L55_Eurotel_Slovakia_001.sim	1		CX654304.xl	CXT65/SK/EUROTTEL
S30880-S7120-U403		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_pl-PTC_50_0409.map /.xfs	L55_PTC-POL_001.sim	1		CX655004.xl	CXT65/PL/ERA/1
S30880-S7120-W100		50 01 00	CX65_1_Standard_50_0001.map	CX65_2_xx-FFS-LG01_50_0471.map /.xfs		0		CX655001.xl	CXT65/INT/TMO
S30880-S7120-W400		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_cz-T-Mobile_50_0471.map /.xfs		0		CX655004.xl	CXT65/CZ/TMO
S30880-S7120-W401		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_at-T-Mobile_50_0471.map /.xfs	L55_Maxmobil_002.sim	1		CX655004.xl	CXT65/AT/TMO
S30880-S7120-W402		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_de-T-Mobile_50_0471.map /.xfs		0		CX655004.xl	CXT65/DE/TMO
S30880-S7120-W404		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_nl-T-Mobile_50_0471.map /.xfs	L55_BEN_001.sim	1		CX655004.xl	CXT65/NL/TMO
S30880-S7120-W405		25 04 00	CX65_1_Standard_25_0001.map	CX65_2_hu-T-Mobile_25_0304.map /.xfs	L55_Westel-Hungary_001.sim	1		CX652504.xl	CXT65/HU/WESTEL/1
S30880-S7120-Z400		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_cz-T-Mobile_50_0471.map /.xfs		0		CX655004.xl	CXT65/CZ/TMO
S30880-S7120-Z401		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_at-T-Mobile_50_0471.map /.xfs	L55_Maxmobil_002.sim	1		CX655004.xl	CXT65/AT/TMO
S30880-S7120-Z402		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_de-T-Mobile_50_0471.map /.xfs		0		CX655004.xl	CXT65/DE/TMO
S30880-S7120-Z404		50 04 00	CX65_1_Standard_50_0001.map	CX65_2_nl-T-Mobile_50_0471.map /.xfs	L55_BEN_001.sim	1		CX655004.xl	CXT65/NL/TMO
S30880-S7120-Z405		25 04 00	CX65_1_Standard_25_0001.map	CX65_2_hu-T-Mobile_25_0304.map /.xfs	L55_Westel-Hungary_001.sim	1		CX652504.xl	CXT65/HU/WESTEL/1
S30880-X7100-A100		12 01 00	CX65_1_Standard_12_0001.map	CX65_2_xx-FFS-LG01_12_0240.map /.xfs	L55_no-id-phone_001.sim	1		CX651201.xl	TU/CX65/NO-ID-PHONE/HIT/A100
S30880-X7100-A101		12 01 00	CX65_1_Standard_12_0001.map	CX65_2_xx-FFS-LG01_12_0240.map /.xfs	L55_no-id-phone_001.sim	1		CX651201.xl	TU/CX65/NO-ID-PHONE/IFX/A101
S30880-X7100-A800		12 08 00	CX6C_1_Standard_12_0001.map	CX6C_2_xx-FFS-LG08_12_0240.map /.xfs	L55_no-id-phone_001.sim	1		CX6C1208.xl	TU/CX65/CHINA/NO-ID-PHONE/HIT/A800
S30880-X7100-U100		12 01 00	CX65_1_Standard_12_0001.map	CX65_2_xx-FFS-LG01_12_0240.map /.xfs	L55_no-id-phone_001.sim	1		CX651201.xl	TU/CX65/NO-ID-PHONE/HIT/U100
S30880-X7100-U101		12 01 00	CX65_1_Standard_12_0001.map	CX65_2_xx-FFS-LG01_12_0240.map /.xfs	L55_no-id-phone_001.sim	1		CX651201.xl	TU/CX65/NO-ID-PHONE/IFX/U101
S30880-X7110-A100		12 01 00	CX6V_1_Standard_12_0001.map	CX6V_2_xx-FFS-LG301_12_0240.map /.xfs	L55_no-id-phone_001.sim	1		CX6V1201.xl	TU/CXV65/NO-ID-PHONE/HIT/A100
S30880-X7110-A101		12 01 00	CX6V_1_Standard_12_0001.map	CX6V_2_xx-FFS-LG301_12_0240.map /.xfs	L55_no-id-phone_001.sim	1		CX6V1201.xl	TU/CXV65/NO-ID-PHONE/IFX/A101
S30880-X7110-U100		12 01 00	CX6V_1_Standard_12_0001.map	CX6V_2_xx-FFS-LG301_12_0240.map /.xfs	L55_no-id-phone_001.sim	1		CX6V1201.xl	TU/CXV65/NO-ID-PHONE/HIT/U100
S30880-X7110-U101		12 01 00	CX6V_1_Standard_12_0001.map	CX6V_2_xx-FFS-LG301_12_0240.map /.xfs	L55_no-id-phone_001.sim	1		CX6V1201.xl	TU/CXV65/NO-ID-PHONE/IFX/U101